

## NOTICE OF SPECIFIED PENALTY

Date of Issue: August 31, 2016

Payment Due Date: September 30, 2016

MSA File Number:	2016-255	<b>Specified Penalty Amount:</b>	\$ 750
Market Participant Name:	TransAlta Generation Partnership		
Asset ID (if applicable):	BOW1	Self Report	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
ISO Rule:	205.6	Date of Contravention:	July 9, 2016
Date of Referral/Self Report:	August 19, 2016	This is the second contravention by this asset for this rule within a rolling 12 month period.	

### EVENT DETAILS

At 08:03 on July 9, 2016, the BOW1 generating asset received concurrent ancillary service directives for 44 MW of spinning reserve and for 80 MW of supplemental reserve, for a total of 124 MW of directed contingency reserve. The BOW1 asset increased generation from 86 MW upon issuance of the directive to 182 MW ten minutes following issuance of the directive. Accordingly, the directive response from BOW1 within the prescribed 10 minute period was approximately 28 MW less than expected. ISO rule section 205.6 indicates that a pool participant must ensure that after receiving a directive to provide supplemental reserve, the asset is providing the quantity of real power equal to the instantaneous amount of real power of the asset at the time of the directive plus the amount of real power set out in the directive, no later than ten minutes after receiving the directive.

### FINDINGS

Based upon the information obtained by the MSA, the MSA is satisfied that the event was a contravention of ISO Rule 205.6.

### MATERIAL FACTS

The material facts relied upon by the MSA include the following:

1. AESO generation, ancillary service dispatch, and ancillary service directive data for BOW1 for July 9, 2016.
2. Self-report from TransAlta Generation Partnership to the MSA dated August 19, 2016.

### DELIVERY OF PAYMENT

Payment by cheque or certified funds is to be made out to the "General Revenue Fund c/o Minister of Finance", and delivered to the Alberta Utilities Commission (AUC) at: 4th Floor, 425 - 1st Street S.W., Calgary, Alberta, T2P 3L8. Questions in respect of delivery of payment should be addressed to the Director of Finance, AUC. The payment should reference this notice and related MSA File #. Delivery of payment should also be confirmed by email to [compliance@albertamsa.ca](mailto:compliance@albertamsa.ca), with copy to the following AUC personnel: Sabi Ghavami (Director, Finance) [sabi.ghavami@auc.ab.ca](mailto:sabi.ghavami@auc.ab.ca), and Andrew Davison (Senior Market Analyst) [andrew.davison@auc.ab.ca](mailto:andrew.davison@auc.ab.ca).

### NOTICE

The Market Surveillance Administrator (MSA) is granted the power and authority under s. 52 of the *Alberta Utilities Commission Act* to issue a Notice of Specified Penalty where the MSA is satisfied that a person has contravened an ISO rule. Specified penalties are set out in AUC Rule 019.

In accordance with the relevant enactments and rules, a dispute regarding the issuance of a Notice of Specified Penalty or failure to pay the specified penalty in accordance with this notice will result in a hearing or other proceeding before the AUC.

In accordance with s. 5(1) of AUC Rule 019 this Notice of Specified Penalty will be made public no earlier than receipt of confirmation of payment from the Commission and no later than 45 days after issuance. The MSA will, if applicable, also post on its website the link to any decision of the AUC respecting the specified penalty.

If your organization disputes the issuance of this Notice of Specified Penalty, or if you have any other questions or comments regarding this matter, please contact the MSA compliance team at [compliance@albertamsa.ca](mailto:compliance@albertamsa.ca).

### SIGNATURE

Signature:	"Original Signed"	Signature Date:	August 31, 2016
Name:	Doug Doll	Title:	Director Corporate Services and Compliance